

Meeting	Planning & Highways
Date	21 st September 2022
Report Title	Haydon View Road
Agenda Reference	6
Author	David Hunt, Head of Parks & Open Spaces

I visited the site of Haydon View Road, Eastville Road, and Sunningdale Road on Monday 5 September 2022 at 8:00 am. These three roads are within Haydon Wick PC but fall into SBC Gorse Hill and Pinehurst Ward I was accompanied on my visit by a resident of Haydon View Road. The resident would like the parish to support him with his approach to SBC.

SBC Highway issues topics that were discussed were,

1. The junction of Haydon View Road and Whitworth Road
 2. Road signage at the junction of Haydon View Road and Sunningdale Road
 3. The poor state of the pedestrian footpath at the junction of Sunningdale Road and Haydon view Road.
-
1. Various road safety considerations at this junction. We observed the traffic on Whitworth Rd at 8:30 am. The traffic flow was constant. There were a considerable number of pedestrians with it being start of school time. The residents' observations were the lack of adequate road markings. These had been present at one time but had now deteriorated. Due to the layout of the mini roundabout motorists coming out of Haydon View Road must stop some distance from the main flow of Whitworth Road traffic. Traffic approaching the roundabout from the East along Whitworth has a tendency not to decrease its speed. The residents suggestions were:
 - a) Road markings are repainted.
 - b) Foliage to the West of the junction is raised to increase vision when drivers are exiting from Haydon View Road. This is a function that HWPC will carry out.
 - c) Foliage to the East of the junction to the front of an HMO be removed to increase vision when drivers are exiting from Haydon View Road. This is a function that HWPC will carry out.
 - d) Extra or larger roundabout signage is erected on the approach to the roundabout from the East.
 - e) The hatched area to the in front of Clarendon Court be extended beyond the Horse Chestnut tree back towards the Cemetery gates, to improve the sight line.
 2. There is no road signage at the junction of Haydon View Road and Sunningdale Road defining where one ends and the other one begins. This has in the past lead to emergency vehicles struggling to locate the correct address. The request is to install:
 - i. Two road name signs at the junction of Haydon View Road and Sunningdale Road. Displaying Haydon View Road and Sunningdale Road with direction arrows.Or
 - ii. One road name sign at the junction of Haydon View Road and Sunningdale Road. Displaying Sunningdale Road.
 3. This has been reported to SBC highways inspectors.